


Vermeer SC252 & SC292

Upgrade Wheel Assembly



If you have any questions or concerns, *please call 1-800-473-3683*



BEFORE YOU BEGIN

Read these instructions completely and carefully

- **Note to installer** – Be sure to leave these instructions for the consumer's use
- **Note to consumer** – Keep these instructions with your Owner's Manual for future reference
- **Skill level** – Installation of the wheel requires intermediate mechanical skills. Proper installation is the responsibility of the installer. Product failure due to improper installation is not covered under any warranty

IMPORTANT - Before you continue, please check the packing list to make sure it matches the contents of the boxes.



Disconnect Power

to machine to prevent any machine components from moving before proceeding. Failure to do so could result in death or serious injury.

FOR YOUR SAFETY read and observe all **CAUTIONS** and **WARNINGS** shown throughout these instructions. While performing the installations that are described in this booklet, gloves & safety glasses or goggles should be worn at all times.



Installation Preparation

TOOLS SUPPLIED:

½" Drive, ½" 6pt Impact Allen Wrench Socket

TOOLS YOU WILL NEED:

5/8" Socket Wrench

½" Drive Torque Wrench

Green-Seize™

TORQUE SETTINGS:

900 Series Nut: 35ft. lbs. (47Nm)

LoPro™ Bolt (lubricated with Green-Seize™): 180 to 200ft. lbs. (244 Nm)

MANUFACTURER'S PARTS LIST:

<i>Part Number</i>	<i>Description</i>
926-WS2	900 Series Wearsharp™ 2-Sided Tooth, For Wheels 22" & Smaller
900LP-A	900 Series LoPro™ Pocket - Angle
LP-200	2" LoPro™ Bolt
ALLENWRENCH-SOCKET	½" Drive, ½" 6pt Impact Allen Wrench Socket

Green Manufacturing, Inc.

9650 Packard Rd

Morenci, MI 49256

Phone 800.473.3683 • Fax 517.458.1550



Table of Contents

Assembly Instructions	4
Upgrade Assembly Diagram	7
Greenteeth® Guarantee	8
Material Safety Data Sheet	9

Assembly Instructions

1. Locate the pocket set with straight pockets on your wheel. **Make sure to refer to the Upgrade Assembly Diagram found on page 7 for the next 28 steps.**
2. Remove one set of straight pockets (Notice you will be leaving this area blank).
3. Proceed to the pocket set below the removed pocket set in step 2. This should be an angle pocket set.
4. Remove the one set of angle pockets (Notice you will be replacing this pocket set with an angle pocket set).
5. Clean both sides where the pockets contact the wheel, with a wire brush. Be sure to remove all dirt and debris so the pocket is seated tightly against the wheel.
6. Apply **Green-Seize™** to the threaded end of two **LoPro™** bolts.
7. Starting with the angle pocket install a **LoPro™** bolt into the counter-bored hole and then do the same of adjacent pocket of that set.
8. Slide the **LoPro™** bolts through the empty holes in the wheel and thread them into the adjacent pocket's threaded holes. For now, firm up the **LoPro™** bolts until pockets are seated. (Figure 1.1)
9. Proceed to the pocket set below the new pocket set installed in step 8. This should be an angle pocket set.
10. Remove the one set of angle pockets (Notice you will be leaving this area blank).
11. Proceed to the pocket set below the removed pocket set in step 10. This should be an angle pocket set.
12. Remove the one set of angle pockets (Notice you will be replacing this pocket set with an angle pocket set).
13. Clean both sides where the pockets contact the wheel, with a wire brush. Be sure to remove all dirt and debris so the pocket is seated tightly against the wheel.
14. Apply **Green-Seize™** to the threaded end of two **LoPro™** bolts.
15. Starting with the angle pocket install a **LoPro™** bolt into the counter-bored hole and then do the same of adjacent pocket of that set.
16. Slide the **LoPro™** bolts through the empty holes in the wheel and thread them into the adjacent pocket's threaded holes. For now, firm up the **LoPro™** bolts until pockets are seated. (Figure 1.1)
17. Proceed to the pocket set below the new pocket set installed in step 16. This should be a straight pocket set.




Figure 1.1

18. Remove the one set of straight pockets (Notice you will be leaving this area blank).
19. Proceed to the pocket set below the space left empty in step 18. This should be an angle pocket set.
20. Remove the one set of angle pockets (Notice you will be leaving this area blank).
21. Proceed to the pocket set below the space left empty in step 20. This should be an angle pocket set.
22. Remove the one set of angle pockets (Notice you will be replacing this pocket set with an angle pocket set).
23. Clean both sides where the pockets contact the wheel, with a wire brush. Be sure to remove all dirt and debris so the pocket is seated tightly against the wheel.
24. Apply **Green-Seize™** to the threaded end of two **LoPro™** bolts.
25. Starting with the angle pocket install a **LoPro™** bolt into the counter-bored hole and then do the same of adjacent pocket of that set.
26. Slide the **LoPro™** bolts through the empty holes in the wheel and thread them into the adjacent pocket's threaded holes. For now, firm up the **LoPro™** bolts until pockets are seated. (Figure 1.11)
27. Proceed to the pocket set below the new pocket set installed in step 26. This should be an angle pocket set.
28. Remove the one set of angle pockets (Notice you will be leaving this area blank).
29. Install your teeth with the carbide facing down. The shoulder of the tooth will meet the flat indent of the pocket and the tooth will not rotate. Insert spacer over shank Chamfer down then thread one of the lock nuts onto the top portion of the tooth. Hand tightening is good for now. Repeat until all teeth are installed. (Figure 1.2)
30. Make sure the pockets are seated on the wheel and the bolts are seated in the pockets. Continue tightening your **LoPro™** bolts until they are all torqued to 180-200 foot lbs. (244 Nm).
31. Before torqueing your tooth down, first make sure that the tooth is seated properly in the pocket. Then tighten the top nut until the tooth is firmly seated and torqued to 35 ft. lbs. (47 Nm). You may need to hold the tooth in place. Repeat until all teeth are properly torqued.





Figure 1.2

Over-tightening the nut will stretch the threads and degrade the fasteners ability to retain the tooth.

32. Once all pockets and teeth are torqued properly start the machine engine and engage the wheel.
33. Ensure there are no noises emanating from the upgrade installation.

Upgrade Assembly Diagram



GREENTEETH™ GUARANTEE

NEW SETUPS AND FIRST TIME CUSTOMERS:

If you purchase a **Greenteeth®** setup and are not completely satisfied with its performance, please contact Green Manufacturing at 800.473.3683 to request a return authorization within 30 days of purchase date for a product refund or exchange.

PRODUCT QUALITY:

We strive to provide exceptional quality product. Our products undergo a stringent quality control process, however if you feel that there is an issue with the quality of your product, please contact Green Manufacturing at 800.473.3683 immediately. We will accept unused parts for return or exchange for up to 30 days from the date of purchase with proof of purchase included with the return.

Greenteeth® is proudly manufactured in the USA by Green Manufacturing, Inc.

Green Manufacturing, Inc.
9650 Packard Rd
Morenci, MI 49256
Phone 800.473.3683 • Fax 517.458.1550



MATERIAL SAFETY DATA SHEET

I - PRODUCT IDENTIFICATION

Trade Name: Tungsten Carbide **Chemical Family:** Refractory Metal Alloy

Chemical Formula: WC **CAS#:** 12070-12-1

II - HAZARDOUS INGREDIENTS

Hazardous Components % OSHA/PEL ACGIH/TLV Sec. 302 Sec. 304 Sec. 313

Tungsten Carbide 0-100 N/E N/E No No No

Tungsten compounds 0-100 5 mg/m3 C - 1 0 mg/m3 No No No

HM IS Ratings (0-4): **Health:** 3 **Flammability:** 0 **Reactivity:** 0

HM IS Protective Equipment: H: glasses, gloves, clothing, combo respirator

III - PHYSICAL DATA

Boiling Point: 6000 oC **Melting Point:** 2820 - 2940 oC

Evaporation Rate: N/A **% Volatiles:** N/A

Solubility in H2O: Insoluble **Vapor Pressure:** N/A

Vapor Density: N/E **Specific Gravity:** 13.6 gm/cc at 18 oC

Appearance and Odor: Grey to black powder, odorless **Molecular Weight:** 195.86

IV - FIRE AND EXPLOSION HAZARDS DATA

Flash Point: N/A **Flammability:** Non-Flammable

Explosive Limits: **Lower:** N/A **Upper:** N/A

Extinguishing Media: Use suitable extinguishing media for surrounding materials and type of fire.

Special Fire Fighting Procedures: Firefighters must wear full face, self-contained breathing apparatus with full protective clothing to prevent contact with skin and eyes. Fumes from fire are hazardous. Isolate runoff to prevent environmental pollution.

Unusual Hazard: Dusts may present a fire or explosion hazard under rare favoring conditions of particle size, dispersion, and strong ignition source. However, this is not expected to be a problem under normal handling conditions.

V - HEALTH HAZARD INFORMATION

Routes of Entry: Inhalation, ingestion, skin or eye contact (for dusts, mists, powder, and fume).

Effects of Overexposure: Industrially tungsten does not constitute an important health hazard. Exposure is related chiefly to the dust arising out of the crushing and milling operations. Chronic inhalation of the dust may cause lung damage in humans. Heavy exposure to the dust or the large amounts of the soluble compounds produces changes in body weight, behavior, blood cells, choline esterase activity and sperm in experimental animals.

Acute Effects:

Inhalation: Toxic by inhalation. May cause irritation to the mucous membranes, coughing, dyspnea, soreness in the chest, weight loss, hemoptysis, bronchitis, asthma, pulmonary fibrosis and radiological changes in the lungs.

Ingestion: May cause irritation to the gastrointestinal tract and diarrhea.

Skin: May cause irritation.

Eye: May cause irritation.

Chronic Effects:

Inhalation: May cause damage to the lungs.

Ingestion: No chronic health effects recorded.

Skin: May cause dermatitis, sensitization and eczema.

Eye: May cause conjunctivitis.

Medical Conditions Generally Aggravated by Exposure: Pre-existing respiratory and skin disorders.

Target Organs: May affect the respiratory system.

Carcinogenicity: NTP: No IARC: No OSHA: No

EMERGENCY AND FIRST AID PROCEDURES:

INHALATION: Remove victim to fresh air. Keep warm and quiet, give oxygen if breathing is difficult and seek medical attention.

INGESTION: If conscious, give 1-2 glasses of milk or water and induce vomiting (Never induce vomiting or give anything by mouth to an unconscious person). Seek medical attention.

SKIN: Remove contaminated clothing from affected area, brush material off skin. Wash affected area with mild soap and water. Seek medical attention if symptoms persist.

EYE: Flush eyes with lukewarm water, lifting upper and lower eyelids, for at least 15 minutes. Seek medical attention if symptoms persist.

VI - REACTIVITY DATA

Stability: Stable

Conditions to Avoid: None

Incompatibility (Material to Avoid): Chlorine, fluorine, nitrogen dioxide, nitrous oxide, iodine pentafluoride and lead oxide.

Hazardous Decomposition Products: None recorded.

Hazardous Polymerization: Will not occur

VII - SPILL OR LEAK PROCEDURES

Steps to Be Taken in Case Material Is Released or Spilled: Wear appropriate respiratory and protective equipment specified in Section VIII. Isolate spill area and provide ventilation. Vacuum up spill using a high efficiency particulate absolute (HEPA) air filter and place in a closed container for proper disposal. Take care not to raise dust.

Waste Disposal Method: Dispose of in accordance with all local, state, and federal regulations.

VIII - SPECIAL PROTECTION INFORMATION

Respiratory Protection: NIOSH approved dust, mist, and vapor cartridge respirator.

Ventilation: Use local exhaust ventilation which is adequate to limit personal exposure to airborne dust levels which do not exceed the appropriate PEL or TLV. If such equipment is not available, use respiratory protection as specified above.

Protective Gloves: Rubber gloves.

Eye Protection: Safety glasses.

Other Protective Clothing or Equipment: Protective gear suitable to prevent contamination.

IX - SPECIAL PRECAUTIONS

Precautions to Be Taken in Handling and Storage: Store in a tightly sealed container in a cool, dry, well-ventilated area. Wash thoroughly after handling.

Other Precautions: Implement engineering and work practice controls to reduce and maintain concentration of exposure at low levels. Use good housekeeping and sanitation practices. Do not use tobacco or food in work area. Wash thoroughly before eating or smoking. Do not blow dust off clothing or skin with compressed air.

The above information is believed to be correct, but does not purport to be all inclusive and shall be used only as a guide. Green Manufacturing, Inc. shall not be held liable for any damage resulting from handling or from contact with the above product.